

**CAMERON BALLOONS LTD (THUNDER & COLT)
SERVICE BULLETIN**

**Subject: THUNDER & COLT
STRATUS BURNER**

**Title: Replacement of valve stems in the main blast, liquid fire
and pilot light valves.**

**Parts affected: 3 valve stems per block in valve blocks with serial
numbers:-**

0001 to 087, 089, 091 to 095, 097, 099, 100, 109, 117.

**(The serial number is engraved on each block and can be
seen when looking down through the coil).**

**Reason for
modification: To ensure prevention of an external propane leak in the
event of valve stem or shutter mechanical failure.**

Classification: Highly recommended.

**Compliance: Within the next 20 flying hours or before 1st July 1996.
(whichever is sooner)**

**Accomplishment
Instructions. Complete the replacement procedure of sections A, B and C
on each affected Valve Block.
Complete section D on each affected Burner/Balloon.**